

Data Center Cooling System Failure

CRAH – Computer Room Air Handler Coils

Jim Dillon, Dorothy Collins and Philip Yu



OPEN
Compute
Project®

Connect. Collaborate. Accelerate.

Background Information

- Low flow through copper coils (0.5 ft/s).
- Stagnant flow, long idle periods due to startup delays and variable use and CRAH rotation.
- Low and stagnant flow in carbon steel chilled water supply piping.
- TES tank issues.
- Treatment program includes PSO (phosphonate), orthophosphate, silicate, benzotriazole, non-oxidizing biocides, caustic (pH control) in softened water.
- Molybdate prohibited due to discharge restrictions. Nitrite not used due to bacteria growth concerns.




OPEN
Compute
Project®




Chilled water leak in CRAH
coil with cooling water and
water solids on fins and in
condensate drip pan

Full scale counts: 1377






OPEN
Compute
Project®



Excessive
condensation
on coil and in drip pan
may be falsely
identified as chilled
water leakage.

Clear condensate
with no water solids.
White zinc corrosion
products and rust
formed due to exposure
of galvanized steel support
to pure water.






OPEN
Compute
Project®

Zinc plating consumed
from galvanized steel
surface exposing steel
which subsequently
rusts



Green patina covering chilled water inlet header and tubes where water vapor condensed from the air. Adjacent outlet header temperature was above the dewpoint, so no condensation occurred there.






U-bends and/or headers on opposite side of tubesheet. Green patina indicates condensation on coil tubes and superficial atmospheric corrosion.



OPEN


Compute
Project®



Green copper corrosion products from copper inlet header and tubes. Dissolved copper ions in condensate will plate out and promote galvanic corrosion of zinc on galvanized steel and on aluminum fins.



OPEN
Compute
Project®



Thermal Energy Storage (TES) Tank stored 500,000 gallons to provide hours of cooling in case chillers shut down. The tank was internally lined with epoxy, but flow inside was essentially stagnant. The tank was not cleaned prior to startup as required because of delays. Consequently, five feet of sludge accumulated on the bottom.

No filters were installed at the outlet as mandated by ASHRAE. The sludge contained substantial amounts of iron oxide, and aerobic bacteria counts were high until after startup when it was shock treated with a bromine product.

The tank wasn't cleaned until at least 7 years following startup, assisted by divers.

TES Tank before System was Commissioned

MICROBIOLOGICAL ANALYSIS

PHYSICAL APPEARANCE

Physical State	Color of Sample	Solids	Color of Solids
Liquid	Colorless	Sediment	Brown

Analyte

Result

Test Method

AEROBIC BACTERIA

Total Viable Count @ 35°C

900000

CFU/mL

CB22010

Pigmented Bacteria

1 Type

Mucoid Bacteria

Detected

Total Coliforms

<100

CFU/mL

E. Coli

<100

CFU/mL

Pseudomonas spp @ 35°C

690000 est.

CFU/mL

ANAEROBIC BACTERIA

Sulfate Reducing bacteria

<1

CFU/mL

CB22016, CB22018

FUNGI

Mold

60 est.

CFU/mL

CB22015

Yeast

<10

CFU/mL

- High aerobic bacteria counts.
- No SRBs or other corrosive bacteria.
- Shock treatment brought bacteria levels under control

Cations - Metals Test Method: CW14024

	Filtered	Total
Aluminum (Al)	<0.03 mg/L	<0.06 mg/L
Barium (Ba)	<0.005 mg/L	<0.010 mg/L
Boron (B)	0.21 mg/L	0.21 mg/L
Cadmium (Cd)	<0.005 mg/L	<0.010 mg/L
Calcium (Ca)	2.7 mg/L	2.7 mg/L
<i>Calcium (CaCO₃)</i>	6.8 mg/L	6.8 mg/L
Chromium (Cr)	<0.016 mg/L	<0.030 mg/L
Copper (Cu)	0.08 mg/L	0.15 mg/L
Iron (Fe)	2.2 mg/L	2.5 mg/L
Lead (Pb)	<0.11 mg/L	<0.20 mg/L
Lithium (Li)	<0.005 mg/L	<0.010 mg/L
Magnesium (Mg)	6.9 mg/L	7.0 mg/L
<i>Magnesium (CaCO₃)</i>	28 mg/L	29 mg/L
Manganese (Mn)	0.027 mg/L	0.055 mg/L
Molybdenum (Mo)	<0.04 mg/L	<0.08 mg/L
Nickel (Ni)	0.02 mg/L	0.03 mg/L
Phosphorus (P)	3.5 mg/L	3.6 mg/L
Potassium (K)	5.4 mg/L	5.7 mg/L
Silicon (Si)	18 mg/L	18 mg/L
<i>Silica (SiO₂)</i>	38 mg/L	38 mg/L
Sodium (Na)	130 mg/L	130 mg/L
<i>Sodium (CaCO₃)</i>	290 mg/L	290 mg/L
Strontium (Sr)	<0.005 mg/L	<0.010 mg/L
Vanadium (V)	<0.01 mg/L	<0.02 mg/L
Zinc (Zn)	<0.01 mg/L	<0.02 mg/L
<i>Total Hardness (CaCO₃)</i>	35 mg/L	36 mg/L

Higher iron concentration
in recirculating chilled water
due to poor maintenance
of TES tank and low and
stagnant flow through carbon
steel piping




One of the coils failed a pressurized air leak test at two locations

- Leaks at end-most tubes connecting unsupported headers to coil tubes.



OPEN

Compute
Project®






OPEN
Compute
Project®



Crack failure

2000μm



Internal deposits but no corrosion. Failure caused by fatigue cracking due to cyclic mechanical stresses by vibration, bending, expansion and contraction. Crack formed at point of stress concentration at sharp edge of brazed joint



OPEN
Compute
Project®




- Fracture at end of tube at interface of brazed joint.
- Tube thickness is about 0.012"
- Inlet tube is about 0.024" thick.

2000 μm




OPEN
Compute
Project®



Through-crack at
galvanized steel header
contact point. Fatigue
crack at point of rigid
restraint. No internal
surface corrosion.



OPEN
Compute
Project®



Fretting wear
on external surface
at tube support
contact.



OPEN
Compute
Project®




Stains suspected to be
cooling water leak sites.

Full scale counts: 2781


Full scale counts: 1377

531 - Location 2 (S004)(1)_pt1






OPEN
Compute
Project®



- Chilled water supply header with inlet port at midpoint.
- Bottom end of header.

Buildup of iron oxide chips and heavy suspended deposits that settled at bottom end of Inlet header. Large chips could not pass through small diameter tube ends, blocking cooling water flow. No strainers or filters upstream of CRAH coils.



Carbon Steel Chilled Water Supply Spool



Piping exposed to water at low flow rates during service and extended idle periods with stagnant flow. Side branches always stagnant. Iron oxide corrosion product tubercles formed in scattered locations.




OPEN

Compute
Project®




OPEN
Compute
Project®

Cleaning revealed
shallow metal loss
at tubercle sites and
away.





OPEN
Compute
Project®



Corrosion isolated and aligned along bottom side of CRAH coil tube where a shallow pool of water collected following drainage causing idle time corrosion. No deposition or copper corrosion products cover bare, shiny surfaces that were well protected.



OPEN

Compute
Project®



Mostly unattacked internal surface covered with thin, black copper oxide layer. Interrupted in scattered sites by shallow pits that are overlaid by corrosion product layers and mounds.


1000µm




OPEN

Compute
Project®

Dried iron oxide and water solid deposits that cracked and spalled after drying. No corrosion on surface beneath.




Wider areas where underdeposit corrosion occurred and where corrosion product mounds spread laterally



OPEN

Compute
Project®






OPEN

Compute
Project®

Corrosion at surface that was partially
occluded by deposits and corrosion
products. Copper oxide filled depression.
Corrosion caused by differential oxygen
Concentration cells and ion concentration cells.



500 μm

Cross-section of
U-bend to CRAH coil
tube brazed joints.
Portions of joints
are not filled, bonded
and sealed properly by
brazing filler metal.





OPEN

Compute
Project®

Ideal gap width for brazed joints is 0.001-0.003" to promote wicking of molten filler metal into joint. The gaps here are greater at about 0.010", which promoted porosity.

2000 μm

Misaligned Tight Joint

Brazing metal did not penetrate and seal the joint. Braze metal only sealed joint outside of the gap in circled locations.



OPEN

Compute
Project®




OPEN

Compute
Project®

Poor fitup weakened the joint. The bend should be installed deeper into the tube end and be filled with braze metal.

2000 μm

- Vertically oriented brazed header joint where zinc chloride flux dripped downward from joint and corroded surfaces below.
- The header was not flushed immediately following brazing to remove residual corrosive flux.






OPEN
Compute
Project®



Corrosion within incompletely sealed
brazed joint for coil tube to U-bend.
Corrosion and corrosion product buildup
extends outward from end of joint.


1000µm





OPEN
Compute
Project®

Crevice corrosion (Concentration cells)



1000 μm



OPEN
Compute
Project®



1 mm

te.


Similar Case from a Third Party Lab

- The accelerated corrosion in the unit analyzed was likely caused by crevices at the straight pipe / U-bend connections in conjunction with the presence of corrosive species in the environment.
- This conclusion was based on the following factors:
 - On the interior of the pipes, the corrosion was concentrated around the straight pipe / U-bend connections.
 - Crevices were observed at these connections.
 - Chlorine and sulfur detected by EDS around the crevices suggests that corrosive ions in the chilled water migrated into the crevices.
 - Crevice corrosion was likely initiated and promoted by detrimental changes in the local chemistry within the crevice, resulting in the accelerated rate of corrosion.
- Crevices can form at the pipe connections due to solder not filling the overlap region. A lack of solder fill may result from:
 - Insufficient or incomplete solder
 - Pipe diameter gap being too large or too small
 - Pipe overlap region being too long


Corrosion on Interior of Pipe



Observed Crevice at Pipe Connection



Crevices cause local stagnation, reduced inhibitor, and a buildup of ion species.



Connect. Collaborate. Accelerate.



OPEN
Compute
Project®



Connect. Collaborate. Accelerate.

Copper and mild steel corrosion rates were always excellent. Coupon testing must be conducted at minimum flow rate of 1.5 ft/s as mandated by ASTM, with no flow variation.

Corrosion Coupon Analysis

Corrosion Rate (Mils per year)

<i>Date</i>	<i>Location</i>	<i>Days</i>	<i>Copper</i>	<i>Mild Steel</i>	<i>70 30 Cu:Ni</i>
5/11/2009	CHW	335	<0.1	1.9	
12/22/2014	CHW	84	0.1	0.3	
4/17/2015	CHW	86	0.1		
4/17/2015	CHW	86		0.4	
4/17/2015	CHW	86	0.1	0.6	
6/29/2015	CHW	217	<0.1	0.4	
6/29/2015	CHW	84	0.1		
6/29/2015	CHW	217		0.5	
6/29/2015	CHW	84	<0.1	0.8	
6/29/2015	CHW	84	0.1		
6/29/2015	CHW	140	0.1	0.6	
10/6/2015	CHW	91	0.1	0.7	
10/6/2015	CHW	91	0.1	0.7	
12/28/2015	CHW	175	<0.1	0.6	
12/28/2015	CHW	115	<0.1	0.2	
12/28/2015	CHW	175	<0.1	0.4	
12/28/2015	CHW	115	<0.1	0.2	
2/19/2016	CHW	86	0.1	0.9	
3/18/2016	CHW	91	<0.1	0.7	
3/18/2016	CHW	91	<0.1	0.4	
3/18/2016	CHW	91	<0.1	0.5	
4/22/2016	CHW	28			<0.1
6/21/2016	CHW	189	<0.1	0.5	
6/21/2016	CHW	70			<0.1
6/21/2016	CHW	98			<0.1

Conclusion

- Low flow through system (0.5 ft/s) promoted settling of suspended solids and corrosion. Low flow reduced replenishment and effectiveness of inhibitors. Minimum flow rate recommended >3 ft/s.
- Stagnant flow, long idle periods promoted corrosion throughout the system
- ASTM prohibits coupon testing when flow rates are less than 1.5 ft/s and must not be variable. Testing under low flow and variable flow conditions will produce questionable results.
- TES tank periodic cleaning not conducted. Filtration required to prevent contamination of the coil tubing.
- Thin, weak, copper tubing was susceptible to fatigue cracking by cyclic applied stresses due to poor design of the coil (unsupported headers, etc.).
- External surface metal loss caused by fretting due to contact with tube supports.
- Poorly constructed and defective brazed joints are weak and susceptible to crevice corrosion.

Other Topic of Interest Design of Cold Plate

Connect. Collaborate. Accelerate.



OPEN
Compute
Project®



OPEN

Compute
Project®



- Very tight fin spacing for cold plate (about 0.005" – or 2 sheets of paper)
- Acts as filter to trap even small suspended solids.

1000 μm

One side of each
fin is rough due to
manufacturing, may
contribute to
solids entrapment.

