


An abstract graphic on the left side of the image, composed of numerous thin, wavy green lines that swirl and overlap to form a complex, organic shape. The lines are a vibrant green color against the dark blue background.

Open. Together.



OCP
SUMMIT

Performance Oriented Firmware Implementation of Error Handling on OCP Platforms for Large Scale Data center



OPEN
PLATINUM™

Zhengyu Yang, Hardware System Engineer, Facebook
Chris Davis, Core Data Production Engineer, Facebook

Agenda

- Generic performance problem on OCP platforms
- Problem diagnose and generic firmware solution
- Results and verification strategy
- Summary




MANAGEMENT



White
Papers

Performance Issues Affects Various OCP Platforms


Platforms Affected in Facebook Fleet



Performance Issue Degrades Availability & Latency

Symptoms Observed in FB production

- Low latency systems like caches experience timeout spikes
- Failures in time critical processes like DB master promotion
- Packet loss, especially impacting new connection attempts
- Higher latencies & error rates in general



Diagnosing & Detecting System Stalls

System Unresponsiveness (a.k.a System Stall)

- Machine functions correctly but stalls for hundreds or even thousands of milliseconds at a time
- “stall” means the machine does 0 work for this time period

Task	Runtime ms	Switches	Average delay ms	Maximum delay ms	Maximum delay at
ksoftirqd/0:3	261.106 ms	166	avg: 25.445 ms	max: 570.087 ms	max at: 12725714.754445 s
rcu_sched:8	640.922 ms	8048	avg: 0.108 ms	max: 381.426 ms	max at: 12725671.219097 s
scribe_cat:(99)	2739.591 ms	1171	avg: 0.349 ms	max: 269.621 ms	max at: 12725714.454340 s
xargs:(18)	2541.290 ms	22096	avg: 0.018 ms	max: 254.727 ms	max at: 12725683.015549 s
kworker/3:0:244396	2.960 ms	121	avg: 2.193 ms	max: 254.498 ms	max at: 12725691.376932 s
ksoftirqd/3:29	3.871 ms	99	avg: 2.751 ms	max: 254.495 ms	max at: 12725691.376942 s
cat:(21992)	23824.856 ms	66206	avg: 0.020 ms	max: 254.491 ms	max at: 12725690.099208 s
carbon-global-s:(3)	446.988 ms	492	avg: 1.647 ms	max: 254.489 ms	max at: 12725691.376856 s
LadDxChannel:2861439	660.121 ms	5147	avg: 0.065 ms	max: 254.454 ms	max at: 12725691.376797 s
FutureTimekeepr:(146)	1963.384 ms	6555	avg: 0.283 ms	max: 254.442 ms	max at: 12725691.376753 s
[xarexec] /usr/:(21)	14159.697 ms	9236	avg: 0.036 ms	max: 254.427 ms	max at: 12725691.376745 s
kworker/1:0:1303233	2.927 ms	131	avg: 2.058 ms	max: 254.426 ms	max at: 12725691.376798 s
ksoftirqd/1:17	5.037 ms	109	avg: 2.447 ms	max: 254.412 ms	max at: 12725691.376817 s

Diagnosing & Detecting System Stalls

Detection

- Detection process simply sleeps and measures how long it actually slept.
- Stalls manifest as a significant delay in waking up.
- Doing this on all cores increases signal

Script for Detecting Stalls


```
while True:  
    start = time()  
    sleep(100ms)  
    elapsed = time() - start  
    if elapsed > 150ms:  
        print("Stall Detected")
```


System Stalls Correlate with Hardware Errors

Correctable Errors are common

```
[12725978.954807] {1861667}[Hardware Error]: Hardware error from APEI Generic Hardware Error Source: 0
[12725978.972915] {1861667}[Hardware Error]: It has been corrected by h/w and requires no further action
[12725978.991358] {1861667}[Hardware Error]: event severity: corrected
[12725979.003874] {1861667}[Hardware Error]: Error 0, type: corrected
[12725979.016388] {1861667}[Hardware Error]: section_type: PCIe error
[12725979.029095] {1861667}[Hardware Error]: port_type: 4, root port
[12725979.041610] {1861667}[Hardware Error]: version: 1.16
[12725979.052407] {1861667}[Hardware Error]: command: 0x0010, status: 0x0547
[12725979.066313] {1861667}[Hardware Error]: device_id: 0000:00:01.0
[12725979.078838] {1861667}[Hardware Error]: slot: 0
[12725979.088590] {1861667}[Hardware Error]: secondary_bus: 0x01
[12725979.100438] {1861667}[Hardware Error]: vendor_id: 0x8086, device_id: 0x6f02
[12725979.115221] {1861667}[Hardware Error]: class_code: 040600
[12725979.126871] {1861667}[Hardware Error]: bridge: secondary_status: 0x2000, control: 0x0013
```



Breakdown of HW Error's Performance Impacting Aspects



Hardware Error Handling Overview

Stack view

- Components
 - Detect, Report and Remediate
- Contributors/Owners
 - **OS & Software** : Harvest failure information and apply remediation method if any
 - **Firmware** : Implement HW error handlers
 - **Hardware**: Provide HW capabilities and error information for error handling




SMM and SEL

- System Management Mode (SMM)
 - Contains SMM HW error handlers
 - Context switch all cores when entered
 - Suppose to be fast
- System Event Log (SEL)
 - Industry standards, allow content customization
 - Created and sent out by BIOS using IPMI commands within SMM
 - IPMI commands can be expensive

Performance Issue Root Cause

System Stall due to SMM & SEL



**Generic problem
due to FW,
across OCP
platforms!**

Performance Focused Hardware Error Handling

FW Solution Strategy


- Failure event based reporting vs. Error occurrence based reporting
- Consolidated, Standardized, Scalable error record
- Overhead minimized error information communication



Performance Focused Hardware Error Handling

FW Solution Example -- BIOS


- Failure Event
 - High Frequency Error Burst
 - Low Frequency Error Tracking
- Unified failure record format



Performance Focused Hardware Error Handling

FW Solution Example – Bridge IC

- Overhead minimized error information communication
 - Ex. “Return first” Model in BIC FW




High-level Flow of HW Error SEL Logging with BIC



Performance Focused Hardware Error Handling

FW Solution Example – BMC


- Overhead minimized error information communication
 - Ex. Enhanced BMC SEL handling flow -- "Ack Quick"*



* Submitted to oBMC committee and pending upcoming spec adoption

Performance Focused Hardware Error Handling


FW Solution Example Results from 3 OCP platforms



Hardware Error SEL logging latency down to as low as 2.34ms

FW Implementation Verification Strategy

- Error Injection
 - HW capability support
 - Error type coverage
- Performance focused
 - Use case driven metrics
 - Quantifiable criteria
- Verification model
 - Performance measured with hardware failures/errors
 - Error occurrences' randomness



Summary


- Hardware error handling caused system performance impact is a common problem across OCP platforms
- Improvements (ex. logging strategy, processing efficiency) can be made at the common firmware layer and applicable to various OCP platforms
- Development and validation of firmware solutions for hardware error handling needs to be system performance aware

Call to Action

- Contribution to OCP (Planned Q3 2019)
 - IPMI SEL HW Error record format and content
 - BIC FW “Return First” Model
 - BMC FW “Ack Quick” SEL processing flow
- Check the fleet
 - OCP system stall in the fleet
 - Correlate system stall with hardware error occurrences
 - Adopt the presented fixing strategy to see improvements



MANAGEMENT



Open. Together.

OCP Global Summit | March 14–15, 2019

